HMAC SIMPLE RULES

Do a Fail Safe & a Range test at the start of the day. Always check control sense before a flight.

Don’t arm a model on a bench. Use the arming tables with the model restrained.

Remove the prop if working on, or programming a live model.

Use a Kill switch when carrying the plane and plug in a Safe tag when it’s in the Pits.

Stay 30M from any person not involved in flying. People may be walking outside our fence.

Call out ‘Launching’ ‘Dead Stick’ & ‘On the Field’ if you are walking on to the field. LOOK FIRST!

Don’t fly over the road. The area marked in pink is a no fly area.

If you crash outside the fence, you must inform an Instructor.

If a model crashes and starts a scrub fire, call 000. There’s fire fighting stuff around the fence.

The Pilot Shed has a First Aid kit and a Defibrillator.

Got Solo or Bronze Wings? Keep it under 2KG RTF please. Over 2KG needs Silver Wings.

You must be fit to fly. No drugs or alcohol. If in doubt, don’t fly. No Smoking near others.

The line of white pavers in front of the flight line is an imaginary fence 400’ high. Stay outside.